

Škoda Karoq

VIN: TMBJG7NU7LJ007420

Diesel

2019

Generat pe 19.02.2025, 07:08



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date



Am verificat 900+ de surse de date în 35 de țări



Fotografii

01.2025

38 de fotografii







Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări:



+2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Lituania



Slovacia



Statele Unite ale Americii



Danemarca



Slovenia



Cehia



Suedia


Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?



Notă

Ultimul kilometraj cunoscut: 144.524 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)



Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat



Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?



Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?



Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 88.029 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Škoda Karoq 2019

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

84.669 RON

Prețul mediu

88.029 RON

Cel mai mare preț

94.320 RON

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Škoda



Model

Karoq



Tip caroserie

SUV



An de fabricație

2019



Capacitate cilindrică

1,6 l



Putere motor

85 kW (114 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie
Tracțiune față (FWD)



Culoare
Negru



Nr. uși
4



Amplasarea volanului
Volan pe stânga



Nr. cilindri
4



Nr. locuri
5



Cod motor
DGTE

Echipare

Cum a fost primit de la producător

0A2

4 DOORS

0B1

WHEELBASE

0EG

INSTALLATION DIFFERENTIATION FOR DUAL-CLUTCH
TRANSV. TRANSMISSION DQ200 -- VEHICLE
COMPONENTS --

0FH

OSNABRUECK MANUFACTURING SEQUENCE

0N1

STANDARD REAR AXLE

0TA

WITHOUT FLOOR MATS

0Y1

STANDARD CLIMATIC ZONES

1AT

ELECTRONIC STABILITY CONTROL (ESC)

0AE

FRONT STABILIZER

0BA

WITHOUT REAR STABILIZER

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0VC

INFORMATION KIT IN GERMAN

0YG

WEIGHT RANGE 7 INSTALLATION CONTROL ONLY, NO
REQUIREMENT FORECAST

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1KE

DISK BRAKES IN REAR

1M6

TRAILER HITCH MECHANICALLY SWIVELING ANDPOWER-DETACHABLE

1NL

TRIMS FOR ALLOY WHEELS

1S3

TOOL KIT

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1Z0

INITIAL STANDARD FUEL FILLING

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2B1

ADDITIONAL EXTERIOR NOISE SUPPRESSION

2JB

STANDARD BUMPERS

2PK

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL W/ TIPTRONIC

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3GA

WITHOUT CARGO AREA

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3N7

MOUNTING FIXTURE IN LUGGAGE COMPARTMENT

3QT

1G8

BREAKDOWN KIT

1L1

AIR CLEANER FOR DUSTY REGIONS

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1PF

STANDARD WHEEL BOLTS

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1X0

FRONT WHEEL DRIVE

1ZE

DISK BRAKES IN FRONT (GEOMET D)

2A0

WITHOUT DELIVERY EQUIPMENT

2H0

WITHOUT "DRIVE SELECT"

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2W6

FUEL FILLER CAP

3CX

NET PARTITION

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3LD

DOOR AND SIDE TRIM PANEL

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3S2

BLACK ROOF RAILS

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER
AND HEIGHT ADJUSTMENT

3T2

THREE REAR HEAD RESTRAINTS

3X0

WITHOUT LOAD-THROUGH HATCH

40N

ALLOY WHEELS 7J X 18

4E6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT
OPENER

4H3

MANUAL CHILD SAFETY LOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM
B-PILLAR AND REAR WINDOW DARK TINTED

4N0

STANDARD DASHBOARD

4R4

POWER WINDOWS WITH COMFORT OPERATION
AND CIRCUIT BREAKER

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

5C0

WITHOUT SPECIAL BODY MEASURES

5J3

ROOF SPOILER

5ML

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5XC

SUN VISORS WITH ILLUMINATED VANITY MIRROR ON
DRIVER AND FRONT PASSENGER SIDE

6E3

CENTER ARMREST IN FRONT

3W3

SPECIAL INTERIOR NOISE SUPPRESSION

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A4

SEAT HEATER FOR FRONT AND REAR SEATS
SEPARATELY CONTROLLED

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY"
WITHOUT SAFELOCK

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-
DIMMING

4P6

REAR FLOOR PANEL MODULE, TYPE 7

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE
AIRBAG AND FRONT PASSENGER AIRBAG
DEACTIVATION

4ZE

BLACK MOLDINGS

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K7

TRANSPORT PROTECTION FILM (MINIMUM
PROTECTION) WITH ADDITIONAL TRANSPORT
PROTECTION MEASURES

5N4

FOLDING GRAB HANDLES, MULTI-PIECE

5SJ

LEFT EXTERIOR MIRROR, CONVEX

5ZF

FRONT HEAD RESTRAINTS

6EA

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6KC

RADIATOR GRILLE

6N0

WITHOUT MUD FLAP

6SE

LUGGAGE COMPARTMENT FLOOR COVERING IN FLAT NEEDLE-PUNCHED NONWOVEN

6XK

EXTERIOR MIRRORS, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

79D

LANE CHANGE ASSIST, LANE KEEPING SYSTEM,TRAFFIC JAM ASSIST, AND EMERGENCY ASSIST

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7LY

VEHICLE CLASS DIFFERENTIATION -5EP-

7N2

SPECTACLE STORAGE COMPARTMENT/BRACKET

7UG

NAVIGATION SYSTEM - HIGH

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

8GU

ALTERNATOR 140 A

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

WITHOUT ADDITIONAL SIDE BODY COVERS (STONE GUARD)

6K3

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "LOW"

6M3

TRUNK NET

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T5

INTERIOR LIGHT IN FOOTWELL IN FRONT AND REAR

77G

DATA STORAGE DEVICE FOR EU, INTEGRATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M0

PLASTIC SCUFF PLATES IN DOOR APERTURES

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7W0

WITHOUT EXTENDED SAFETY SYSTEM

8G1

HIGH-BEAM CONTROL

8IX

LED HEADLAMPS WITH CORNERING LIGHT (SEPARATE DAYTIME RUNNING LIGHTS WITH SPECIAL CLASS-A SURFACE)

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8QL

KEY FOR LOCKING SYSTEM WITH REMOTE CONTROL

8S6

2 READING LIGHTS IN FRONT

8TB

REAR FOG LAMP

8WH

FRONT FOG LAMP AND CORNERING LAMP

8Y1

TWO-TONE HORN

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9JA

NON-SMOKER'S PACKAGE

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9T1

HEATED WASHER NOZZLES IN FRONT

9U1

BRAKE PAD WEAR INDICATOR

9Z0

OPERATING VOLTAGE 12 V

A8D

LUXURY EQUIPMENT

B01

TYPE APPROVAL COUNTRY GERMANY

C12

OPERATING PERMIT, ALTERATION

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8RM

8 SPEAKERS (PASSIVE)

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8W1

WASHER FLUID LEVEL INDICATOR

8X1

HEADLAMP WASHER SYSTEM

8Z5

NOT HOT COUNTRY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9J0

WITHOUT SUPERTONE SYSTEM AND TONE SEQUENCE CONTROL

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9S6

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"COLOUR"

9TC

ADDITIONAL REFLECTORS (DOOR AREA)

9WT

MIRRORLINK

9ZC

COMFORT TELEPHONY WITH EXTERIOR ANTENNA AND (RSAP)

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

DK8

4-CYL. TURBO DIES. ENG. 1.6 L/85 KW 4V TDI
COMMON RAIL BASE ENGINE IS TJ1/TI7

E0A

NO SPECIAL EDITION

EF0

WITHOUT ECO FUNCTION

EM1

DRIVER ALERT SYSTEM

ES0

WITHOUT VEHICLE INLET

FB0

STANDARD PAINT COATING

G02

SHOCK ABSORPTION IN FRONT

GM1

STANDARD ELECTRONIC ENGINE SOUND

IA0

WITHOUT BRACKET

IN1

REAR AXLE WEIGHT, TYPE 1

K8P

MPV

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

ND1

ADAPTER

Q2J

COMFORT SEATS IN FRONT

QE5

STORAGE COMPARTMENT PACKAGE 3

QH1

VOICE CONTROL

QJ3

CHROME PACKAGE (TYPE 2)

EA0

WITHOUT FOLLOW-ON WARRANTY

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD
UNITCODING, WITHOUT ENGINE IMMOBILIZER
INTERCONNECTION

ER1

REGIONAL CODE " ECE " FOR RADIO

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD
EQUIPMENT

FM0

BASIC EQUIPMENT VARIANT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

I8J

RADIO HIGH (GEN2 GP)

IG1

CURB WEIGHT RANGE 1

J0V

BATTERY 420 A (70 AH)

KA1

WITH REAR VIEW CAMERA SYSTEM (TYPE 1)

L02

SUSPENSION RANGE 02 INSTALLATION CONTROL
ONLY, NO REQUIREMENT FORECAST

N3C

SEAT TRIM COVERS IN FABRIC

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q46

TIRES 215/50 R18 92W LOW ROLLING RESISTANCE

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QK1

WITH MULTIFUNCTION CAMERA

QQ9

INTERIOR AMBIENT LIGHTING, TYPE 2

QV3

DIGITAL RADIO RECEPTION

TJ1

4-CYLINDER DIESEL ENGINE 1.6 L UNIT 04L.1

UC7

REAR SHOCK ABSORPTION, SUSPENSION WITH INCREASED RIDE HEIGHT

UH2

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

VF0

STANDARD PEDAL CLUSTER

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

S4V

REGION

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG1

HILL START ASSIST

UI5

ELECTRIC INTERFACE FOR EXTERNAL USE, USB (IPOD-CAPABLE)

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

Cronologie

S-au găsit 3 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2019 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

09.2019 🌐 Țară necunoscută



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

01.2025 🇩🇪 Germania



A fost la vânzare

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**